



Chicago, O'Hare International Airport

Common Use Gate Capacity : March 28 - October 30, 2021



| Position | Terminal | Concourse | Aircraft that can be accommodated at Position | | | | | | | | | | | | | | | | | | | | |
|----------|----------|-----------|---|------|--------|--------|--------|-------|--------|--------|----------|--------|-------|-------|--------|---------|---------|---------|---------|--------|---------|---------|---------|
| L11A | 3 | L | C208 | C402 | B19C | PC12 | P2012 | | | | | | | | | | | | | | | | |
| L11B | 3 | L | C208 | C402 | B19C | PC12 | P2012 | | | | | | | | | | | | | | | | |
| M1 | 5 | M | E175 | E190 | A319-2 | A320-2 | A321-2 | B73-9 | B75-2W | B75-3W | B76-3ERW | | | | | | | | | | | | |
| M2 | 5 | M | E175 | E190 | A319-2 | A320-2 | A321-2 | B73-9 | B75-2W | B75-3W | B76-3ERW | | | | | | | | | | | | |
| M3 | 5 | M | E175 | E190 | A319-2 | A320-2 | A321-2 | B73-9 | B75-2W | B75-3W | B76-3ERW | A330-3 | B78-8 | B78-9 | B78-10 | B77-2ER | B77-3ER | A350-9 | A350-10 | A340-6 | B74-4ER | | |
| M4 | 5 | M | E175 | E190 | A319-2 | A320-2 | A321-2 | B73-9 | B75-2W | B75-3W | B76-3ERW | A330-3 | B78-8 | B78-9 | B78-10 | B77-2ER | B77-3ER | A350-9 | A350-10 | A340-6 | B74-4ER | | |
| M5 | 5 | M | E175 | E190 | A319-2 | A320-2 | A321-2 | B73-9 | B75-2W | B75-3W | | | | | | | | | | | | | |
| M6 | 5 | M | CLOSED | | | | | | | | | | | | | | | | | | | | |
| M7 | 5 | M | E175 | E190 | A319-2 | A320-2 | A321-2 | B73-9 | B75-2W | B75-3W | B76-3ERW | A330-3 | B78-8 | B78-9 | B78-10 | B77-2ER | B77-3ER | A350-9 | | | | | |
| M7A | 5 | M | E175 | | | | | | | | | | | | | | | | | | | | |
| M7B | 5 | M | E175 | E190 | A319-2 | A320-2 | A321-2 | B73-9 | | | | | | | | | | | | | | | |
| M8 | 5 | M | E175 | E190 | A319-2 | A320-2 | A321-2 | B73-9 | B75-2W | B75-3W | B76-3ERW | A330-3 | B78-8 | B78-9 | | | B77-2ER | B77-3ER | A350-9 | | | A340-6 | B74-4ER |
| M9 | 5 | M | E175 | E190 | A319-2 | A320-2 | A321-2 | B73-9 | B75-2W | B75-3W | B76-3ERW | A330-3 | B78-8 | B78-9 | B78-10 | B77-2ER | B77-3ER | A350-9 | A350-10 | A340-6 | B74-4ER | | |
| M10 | 5 | M | E175 | E190 | A319-2 | A320-2 | A321-2 | B73-9 | B75-2W | B75-3W | B76-3ERW | A330-3 | B78-8 | B78-9 | B78-10 | B77-2ER | B77-3ER | A350-9 | A350-10 | A340-6 | B74-4ER | | |
| M11 | 5 | M | E175 | E190 | A319-2 | A320-2 | A321-2 | B73-9 | B75-2W | B75-3W | B76-3ERW | A330-3 | B78-8 | B78-9 | B78-10 | B77-2ER | B77-3ER | A350-9 | A350-10 | A340-6 | B74-4ER | B74-8 | |
| M11A | 5 | M | A380-8 | | | | | | | | | | | | | | | | | | | | |
| M12 | 5 | M | E175 | E190 | A319-2 | A320-2 | A321-2 | B73-9 | B75-2W | B75-3W | B76-3ERW | A330-3 | B78-8 | B78-9 | B78-10 | B77-2ER | B77-3ER | A350-9 | A350-10 | | | B74-4ER | |
| M13 | 5 | M | E175 | E190 | A319-2 | A320-2 | A321-2 | B73-9 | B75-2W | B75-3W | B76-3ERW | A330-3 | B78-8 | B78-9 | B78-10 | B77-2ER | B77-3ER | A350-9 | A350-10 | A340-6 | B74-4ER | B74-8 | |
| M15 | 5 | M | E175 | E190 | A319-2 | A320-2 | A321-2 | B73-9 | B75-2W | B75-3W | B76-3ERW | A330-3 | B78-8 | B78-9 | B78-10 | B77-2ER | B77-3ER | A350-9 | A350-10 | A340-6 | B74-4ER | | |
| M16 | 5 | M | E175 | E190 | A319-2 | A320-2 | A321-2 | B73-9 | B75-2W | B75-3W | B76-3ERW | A330-3 | B78-8 | B78-9 | B78-10 | B77-2ER | B77-3ER | A350-9 | A350-10 | A340-6 | B74-4ER | B74-8 | |
| M17 | 5 | M | E175 | E190 | A319-2 | A320-2 | A321-2 | B73-9 | B75-2W | B75-3W | B76-3ERW | A330-3 | B78-8 | B78-9 | B78-10 | B77-2ER | B77-3ER | A350-9 | A350-10 | A340-6 | B74-4ER | | |
| M18 | 5 | M | E175 | E190 | A319-2 | A320-2 | A321-2 | B73-9 | B75-2W | B75-3W | B76-3ERW | A330-3 | B78-8 | B78-9 | B78-10 | | | | | | | | |
| M19 | 5 | M | E175 | E190 | A319-2 | A320-2 | A321-2 | B73-9 | B75-2W | B75-3W | B76-3ERW | A330-3 | B78-8 | B78-9 | | | | | | | | | |
| M20 | 5 | M | E175 | E190 | A319-2 | A320-2 | A321-2 | B73-9 | B75-2W | B75-3W | B76-3ERW | A330-3 | B78-8 | B78-9 | B78-10 | | | | | | | | |
| M21 | 5 | M | E175 | E190 | A319-2 | A320-2 | A321-2 | B73-9 | B75-2W | B75-3W | B76-3ERW | A330-3 | B78-8 | B78-9 | B78-10 | B77-2ER | B77-3ER | A350-9 | A350-10 | A340-6 | B74-4ER | | |
| M22 | 5 | M | E175 | E190 | A319-2 | A320-2 | A321-2 | B73-9 | B75-2W | B75-3W | B76-3ERW | A330-3 | B78-8 | B78-9 | B78-10 | B77-2ER | B77-3ER | A350-9 | A350-10 | A340-6 | B74-4ER | | |
| M22A | 5 | M | E175 | E190 | A319-2 | A320-2 | A321-2 | B73-9 | | | | | | | | | | | | | | | |
| M22B | 5 | M | E175 | E190 | A319-2 | A320-2 | A321-2 | B73-9 | | | | | | | | | | | | | | | |



Chicago, O'Hare International Airport

Common Use Hardstand Capacity : March 28 - October 30, 2021



| Position | Terminal | Concourse | Aircraft that can be accommodated at Position | | | | | | | | | | | | | | | | | | | | |
|----------|----------|-----------|---|------|--------|--------|--------|-------|--------|--------|----------|--------|-------|-------|--------|---------|---------|--------|---------|--------|---------|-------|--------|
| 101 | 5 | Remote | E175 | E190 | A319-2 | A320-2 | A321-2 | B73-9 | B75-2W | B75-3W | B76-3ERW | A330-3 | B78-8 | B78-9 | B78-10 | B77-2ER | B77-3ER | A350-9 | A350-10 | A340-6 | B74-4ER | | |
| 102 | 5 | Remote | E175 | E190 | A319-2 | A320-2 | A321-2 | B73-9 | B75-2W | B75-3W | B76-3ERW | A330-3 | B78-8 | B78-9 | B78-10 | B77-2ER | B77-3ER | A350-9 | A350-10 | A340-6 | B74-4ER | | |
| 103 | 5 | Remote | E175 | E190 | A319-2 | A320-2 | A321-2 | B73-9 | B75-2W | B75-3W | B76-3ERW | A330-3 | B78-8 | B78-9 | B78-10 | B77-2ER | B77-3ER | A350-9 | A350-10 | A340-6 | B74-4ER | | |
| 103A | 5 | Remote | A380-8 | | | | | | | | | | | | | | | | | | | | |
| 104 | 5 | Remote | E175 | E190 | A319-2 | A320-2 | A321-2 | B73-9 | B75-2W | B75-3W | B76-3ERW | A330-3 | B78-8 | B78-9 | B78-10 | B77-2ER | B77-3ER | A350-9 | A350-10 | A340-6 | B74-4ER | B74-8 | |
| 104A | 5 | Remote | E175 | E190 | A319-2 | A320-2 | A321-2 | B73-9 | | | | | | | | | | | | | | | |
| 104B | 5 | Remote | E175 | E190 | A319-2 | A320-2 | A321-2 | B73-9 | | | | | | | | | | | | | | | |
| 105 | 5 | Remote | E175 | E190 | A319-2 | A320-2 | A321-2 | B73-9 | B75-2W | B75-3W | B76-3ERW | A330-3 | B78-8 | B78-9 | B78-10 | B77-2ER | B77-3ER | A350-9 | A350-10 | A340-6 | B74-4ER | | |
| 106 | 5 | Remote | E175 | E190 | A319-2 | A320-2 | A321-2 | B73-9 | B75-2W | B75-3W | B76-3ERW | A330-3 | B78-8 | B78-9 | B78-10 | B77-2ER | B77-3ER | A350-9 | A350-10 | A340-6 | B74-4ER | | |
| 107 | 5 | Remote | E175 | E190 | A319-2 | A320-2 | A321-2 | B73-9 | B75-2W | B75-3W | B76-3ERW | A330-3 | B78-8 | B78-9 | B78-10 | B77-2ER | B77-3ER | A350-9 | A350-10 | A340-6 | B74-4ER | | |
| 107A | 5 | Remote | E175 | E190 | A319-2 | A320-2 | A321-2 | B73-9 | B75-2W | B75-3W | B76-3ERW | A330-3 | B78-8 | B78-9 | B78-10 | B77-2ER | B77-3ER | A350-9 | A350-10 | A340-6 | B74-4ER | B74-8 | AN-124 |
| 107B | 5 | Remote | E175 | E190 | A319-2 | A320-2 | A321-2 | B73-9 | | | | | | | | | | | | | | | |
| CD1 | Deicing | Remote | E175 | E190 | A319-2 | A320-2 | A321-2 | B73-9 | | | | | | | | | | | | | | | |
| CD2 | Deicing | Remote | E175 | E190 | A319-2 | A320-2 | A321-2 | B73-9 | | | | | | | | | | | | | | | |
| CD3 | Deicing | Remote | E175 | E190 | A319-2 | A320-2 | A321-2 | B73-9 | | | | | | | | | | | | | | | |
| CD4 | Deicing | Remote | E175 | E190 | A319-2 | A320-2 | A321-2 | B73-9 | | | | | | | | | | | | | | | |
| CDW | Deicing | Remote | E175 | E190 | A319-2 | A320-2 | A321-2 | B73-9 | B75-2W | B75-3W | B76-3ERW | A330-3 | B78-8 | B78-9 | B78-10 | B77-2ER | B77-3ER | A350-9 | A350-10 | A340-6 | B74-4ER | | |